

# VILLAGE OF MUNDELEIN

Compliance

Marilyn Sindles, Mayor

Pamela Keeney, Clerk

440 East Hawley Street Mundelein, IL 60060 www.mundelein.org Telephone: (847) 949-3200 Fax: (847) 949-0143

info@mundelein.org

August 30, 2002

DECEIVE N SED 4 2002

Illinois Commerce Commission
RAIL SAFETY SECTION

Mr. Bob Berry Illinois Commerce Commission Transportation Division/Railroad 527 E. Capitol Ave. P. O. Box 19280 Springfield, IL 62794-9280

TO1-0029

Dear Bob:

Enclosed is the automated horn system monthly report for the month of August 2002. Included with this month's report are the minutes from the automated horn system quarterly meeting required by the ICC order to review the operation of the system, and my letter of August 28, 2002 to Kurt Anderson regarding the blinders that were installed on the confirmation signals.

Also attached is a report from Railroad Controls showing all of the calls for service at the Mundelein locations from March 16-August 22, 2002. Some of these incidents were not previously included in my monthly report. As you will notice, since the train horns stopped on April 12, 2002 there have been a total of 12 incidents that required service calls.

Sincerely,

Michael A. Flynn

Assistant Village Administrator

MAF/ch Enclosure

cc: Kurt Anderson, Railroad Controls Ltd.

Ronald Ries, U.S. Department of Transportation

Anya Carroll, Volpe National Transportation Systems Center

Tammy Wagner, Federal Railroad Administration

Dennis Mogan, Metra

Chip Pew, Illinois Commerce Commission

DOCKETED



**COMMENTS** 

# VILLAGE OF MUNDELEIN AUTOMATED HORN SYSTEM MONTHLY REPORT TO THE ILLINOIS COMMERCE COMMISSION

FOR REPORTING PERIOD AUGUST 1, 2002 TO AUGUST 31, 2002

<u>OPERATIONS</u>	
Total of operational problems reported	2
CITIZEN COMMENTS	
Total of citizen comments related to automated horn system _	9
Positive <u>5</u> Negative <u>4</u>	
Total of citizen complaints related to train whistles	0
GATE VIOLATIONS	
Number of tickets issued for crossing violations for this reporti	ng period 2
Was enforcement of crossings conducted during the reporting period?Yes	Total hours 4 minutes

# AUTOMATED TRAIN HORN ACTIVITY REPORT

## August 9, 2002

1.	Comment	Letter complaining about AHS (see attached).
	William Palisek	
	1294 Banbury Road	
}	847-566-1888	

#### August 12, 2002

1.	Comment	E-mail from newspaper editor praising AHS (see attached).
	Bob Diedrich	
	Northwest Herald	
	815-385-0170	
2.	Comment	Phone call praising the AHS.
	Arian Haight	
	201 S. Chicago	
	847-837-8014	

#### August 14, 2002

1.	Comment	Phone call and visit to Village Hall complaining abut AHS,
	Norman Haley	especially the number of times the horn sounds. Cannot sleep at
	306 Dunbar	night.
	847-566-6291	

# August 17, 2002

1.	Comment	E-mail praising the AHS (see attached).
	Chris and Karen Anderson	
	1713 Dorchester Ct.	

## August 20, 2002

1.	Comment	Resident stopped by Village Hall to report the horn is very loud and
		long when person is walking across railroad crosswalk.
2.	Comment	E-mail praising the AHS (see attached).
	Steve & Betty Kaminsky	
	501 Killarney Pass Circle	
	847-566-1918	·

## August 21, 2002

1.	Operational Problem	Canadian National Dispatch reported no confirmation signal at
	(AHS confirmation signal)	Dunbar crossing.

## August 21, 2002

1.	Operational Problem	Canadian National Dispatch reported power supply damaged at
		Route 60 crossing.

# AUTOMATED TRAIN HORN ACTIVITY REPORT

# August 23, 2002

1.	Comment	Dropped off petition signed by 75 people against the AHS (see
	Ms. Johnson	attached).
	Corner Health Food Store	
	Park & Seymour Streets	

## August 24, 2002

1.	Comment	E-mail praising the AHS (see attached).
	Kathy Hedberg	
	Holcomb Subdivision	

#### August 27, 2002

1.	Obstruction of Highway	Ticket issued to Canadian National for blocking Dunbar crossing
	Mundelein Police Dept.	from 2:11 a.m. to 3:16 a.m. for a total of 1 hour and 5 minutes.
2.	Obstruction of Highway	At 7:29 a.m. train was blocking crossing on Allanson Rd.
	Mundelein Police Dept.	

#### August 29, 2002

1. Obstruction of Highway	Ticket issued to Canadian National for blocking Allanson Road
Mundelein Police Dept.	crossing at 11:38 p.m. for a total of 12 minutes.

1294 Banbury Road – Mundelein, IL – 60060 / Phone 847-566-1888 / E-Mail Munbill@aol.com

August 9, 2002

Mayor Sindles Village Hall 440 E. Hawley Street Mundelein, IL 60060

Dear Ms. Mayor;

The steam locomotive was invented in the early 19<sup>th</sup> century. They used a steam whistle to alert traffic of an oncoming train. Apparently railroaders' thinking has not progressed beyond that point in time. With all the technology we have today their must be a better way to satisfy everyone's concerns.

I have a few comments and suggestions in regard to the Automated Train Horns at the Dunbar crossing:

- 1. The people who gave us a demonstration of the proposed automated horns a year or so ago misled us. The sound they demonstrated was nowhere as loud or as shrill as the horns that where installed.
- 2. The whole point of the horn system is to warn the traffic sitting at the crossing gate of an approaching train. Due to the unique layout of this crossing the horn facing West should have been placed 50 feet further West and facing East at the traffic at the gate and towards the uninhabited woods across the Rt.45 instead of blasting directly into our homes.
- 3. The horns should be integrated with the traffic sensors under the road and not be activated if there is no one at the crossing. During the night there is little or no traffic at all
- 4. The horns should not break the silence with a 100db or louder blast, instead they should ramp up to their maximum volume to mimic an approaching train and be less jarring on the nerves.
- 5. In the past the trains did not sit at the crossing and sound there horns ten or twelve times at full volume. This is in fact what we have to endure.
- I do work in Glennview, Northbrook, Lake Forest, and Deerfield and none of these towns have to put up with the train horns. The trains run silent 98% of the time
- Install double action gates: the gates will lower as they do now, after a 10 second delay a secondary arm would come down to extend the gate all the way across the roadway. The delay would allow traffic to clear the crossing.
- 8. In a perfect world. Eliminate the crossing altogether and relocate the traffic over a causeway built over the dam and let the traffic leave the subdivision trough the Edgemont intersection.

I realize the horns alleviated the noise pollution for a lot of my neighbors, but for those of us near them it is intolerable. Any thing that can be done to help will be greatly appreciated.

William afisek

Regards,

Copy: M. Flynn

#### Ken Marabella

From: Sent: To: Bob Diedrich [bdiedrich@nwherald.com] Monday, August 12, 2002 11:24 PM

To: Subject: Ken Marabella columns

Enjoy.

Did you find the CL fiasco online?

The first is the recent one about Metra's expansion. It ran June 3.

A NIMBY issue has surfaced in my back yard.

And unlike Algonquin trustees who removed the Routes 31-62 northern bypass corridor from their comprehensive plan, I will not join the "not in my back yard" McHenry residents who are attempting to squash a Metra rail yard in Johnsburg.

See, the train tracks run along the western edge of my subdivision. Tracks that were in plain view of any perspective home buyer who can examine a map, including myself.

Tracks that during my youth carried passengers from Chicago to Lake Geneva on weekends. Tracks that stopped being used, but always remained viable as a future transportation corridor.

And tracks have always carried only one thing: trains.

When details of Metra's expansion plan materialize, it should provide effective safeguards, proper screening and limited noise impact for residents.

However, McHenry residents must remember the issue will be decided by Johnsburg trustees, not one of which is elected by McHenry residents. Wanting to examine the issue firsthand, I traveled to Mundelein to view an experimental program that has replaced train blasts with a lower impact automated train horns.

The horns are emitted from stereo speakers mounted at intersections and concentrate the sound at the crossing. The system reduces noise pollution by 97 percent, affecting about 5 acres instead of 171 acres.

Sitting in direct sight two blocks away at Mundelein's city hall, I could have had a conversation without raising my voice. Metra spokesman Tom Miller said cities can request and pay for the devices at a average cost of \$52,000 per location. There are 16 months left of study, but there is no reason to wait for the results. The devices should be put at every rail crossing. In addition, I took an unannounced tour of Metra's rail yard in Antioch. Although smaller in scope than the Johnsburg proposal, the yard was well kept and well screened from a neighboring subdivision that contained two-story, single-family homes similar to those in McHenry's Mill Pond and Millstream subdivisions.

McHenry residents should be given a tour of both locations so they can hear Mundelein's whistles and see Antioch's rail yard.

Metra's plan for Johnsburg also must address train speeds and safety issues, but as a concept, I can't argue against efficient transportation.

Like the addition of Route 53, more trains would provide an alternative to motorists locked in traffic.

And being a lifelong Cubs fan, it's always a benefit when Wrigley Field can be brought to your doorstep. Even if the team has no offense.

Bob Diedrich is a Northwest Herald community editor. He may be reached via e-mail at northbureau@nwherald.com or by calling (815) 385-0170.

This is the one I wrote after the police chief resigned.

AHS for Aug Report

#### Michael Flynn

From:

Ckbhanderson@aol.com

Sent:

Saturday, August 17, 2002 10:18 AM

To:

mflynn@mundelein.org.

Subject: Automated Horn System

Dear Mr. Mike Flynn;

My name is Chris Anderson and me and my family live on Dorchester Court which is just past Village Green Golf Course on Midlothian. We live right off the road Midlothian; thus, we hear the train whistles at the railroad crossing at h.w. #45 and Winchester. I am not sure on the exact distance we live from the crossing but it is approx. two miles.

Bottomline, we are definately supporters of having the ICC continue to use the Automated Horn system as it is clearly loud at the necessary location but not intrusive to neighbouring residents. Also, the flashing "X" also helps the driver zone in on the fact that he/or she is driving up to a railroad crossing. I think I am right at the threshold of the distance to hear the automated horn sytem but it is not nearly as loud as the locomotive engineers manual honking.

The other point I have for the ICC is that this automated horn system provides a consistent volume and duration rather than the inconsistent volume and duration levels reached by the manual honking method by locomotive engineers. There are times where it is so loud and continuous that it makes me think that the engineers are thinking: well, if I have to be awake in the middle of the night, so can you. I recognize in the case of an emergency, the engineer can also honk the horn manualy.

I think this is a step in the right direction for both safety and urban planning and should be continued and used elsewhere.

Thanks,

Yours Truly,

Chris and Karen Anderson 1713 Dorchester Court Mundelein

#### Michael Flynn

From:

skaminsky@firstambank.com

Sent:

Wednesday, August 21, 2002 3:15 PM

To:

Michael Flynn

Subject:

Automated Horn System

Mike,

My wife and I are thrilled with the Automated Railroad Horn System! We live in Loch Lomand. Before this system, the horn sound would come rolling off the Lake. This has improved the peace and quiet immensely.

Thank you so much!

Steve & Betty Kaminsky 501 Killarney Pass Circle Mundelein, Il. 60060 847-566-1918

AUG 1 9 2002 Address Name N. Seymour are. in L 6062

Name	Address
1. Market	Hematy, 506 N. SEYMOUR MUND.
2. Authre	1 19 824 Brainar Dr. Mundelein
3. Mally	9 Ryan 407 N Lake shore Or Mund.
A	Reguras 1280 Duerdeen Mund IL
5. Jonnifer	Sonnewberg 343 Greenview Avenue Mund. &
	SODGE SOU N. PRAIRE MUNDELEIN
7. SUE HEF	ERNAN 3917 WOOD CREEK, ISLANDLAKE, IL
8. Andrei A	regni-Rad 1310 St. William Dr. Libert, ville IL
9	
10	
11	
12	
13	
14	
15	
16	
17	,
18	
22	

Name	Address .
1. 5 Aben order	34Z E. PARIC
2. P. Clendering	402 E. Park.
3. a. Whatte	1350 Park.
4. K. Nelm	300 E. Park
5. Judiel & Behm	300 E. Park
6. Jan Salin	300 E PARK
1. They Maymon	_ ZOI E. Park
8. Kny lin Josephin	205 E. Park
9. Jama Manylve	1 205 E. Park
10. Noboa J Colin	a 100 W Howly St
11. Spea Stabe	- 4218. Maple live
12. Jeana Sca	helig 406 E. Park at.
13. Jacque M. Houlans	2 521 Grove One Mundelson De
14. Dund Kusti	343 E. Wysle
15. Temperay Time	achar 337 E. MAPCE
16.	327 E- 19217=
17. Leslie Molman	301 E. Maple
18. Chris Molnar	301 E. Maple
19. Cathign Jouph	1
20. Most flirewith	- 19588 W. Thore Dr.
2 Junelle Ceell	
22. Taura Joffes	edo 231 E. Naple
	$m{l}$



Name	Address	
1/15A Meyer	210 E. Hawley	
2 Jerry Boka	and -344 Yorkshire De 401 N. Symour	
3. J. M. Was	HOI N. Segmour	,
4		
5		
6		
7		
8		
10		
11		
12		
13	•	
14		
15		<del></del>
16		
17,		
19		<del></del>
		<del></del>
22		

	Name	Address
	1. Ma	non-Chamberian 1001 Down Ct. Libertyville. St.
	2. Bia	way Wieter 912 mckindey Dr. mundalein
	3. NVUC	auto Ila, 585 Shaddhe Mundalein, IL
		e Tobben 133 n. Idlewild, Mundelein, IL
ut old war which	5. Holl the Cean	miller 201 E. Cuchaire Liberty mète de 60048 60048_ un Konsisiége 100 P.O. Bx 134 Kiderty xy (los) 60048_
Macro	7. M	antila 1771 Bambill Dr.; Mondian 60060
•	8. Dela	Vallmild 251 Vieta Rd. Lake Gurech (00047
		Whe 225 Goodwindle. Mund. Illa 0060
		ulto Alber 225 Goodwin Mirsel 60060
		ndy Bouch 1025 walnut at Mendelein
		en le Presquer 33446/ Nove JCt Wildwood 60030
	<u> </u>	ogy Runsfield 416 Horrison A. Vernon Hells 60061
	14.	aldine Yolary 406 w. Livesion Munklain, I 60000
	15.	POLIDORD 305 S. Lakeshore Do Mundolevill 60000
	16	Se DOM 109 S California Mondellin 60060
	17	IN HOUSE 65 78 R.F.D Long GOOD 60047
	18.//)	exceles Lenge 39044 11. Gilme Od Mundelon, 60060
•	19. Sh	erry Corder 85 N. Crescent, Mundelein 60060
	20. <b>L</b>	to Cityan 59 Shady Love Mundelein 60040
	21	
	22.	

#### Michael Flynn

From: Kathy Hedberg [kpegg@corecomm.net]

Sent: Saturday, August 24, 2002 2:45 PM

To: Michael Flynn

Subject: Automated Horn System

Dear Mr. Flynn,

I think the automated horn system that was installed at the intersection of 176 and Jeannette in Mundelein, has made a world of difference in the Holcomb subdivision. As a resident in this subdivision, and living near the tracks, the new system has not interrupted my family time in the evenings as well as during the middle of the night when the trains roll by. My of my neighbors has expressed "How nice it is not to hear the train beep their horns in the middle of the night". I commend the village and the ICC in their efforts in to minimize the sound pollution in our area. I hope this is a permanent decision by the village and the ICC to keep the automated horn system in place.

Sincerely,

Kathy Hedberg

# AUTOMATED HORN SYSTEM QUARTERLY MEETING MINUTES AUGUST 22, 2002

Attendance:

Mike Barron (Canadian National), Jack Palach (Canadian National), Mike

O'Brien (Village of Mundelein), Mike Flynn (Village of Mundelein)

Also in attendance:

Chip Pew (ICC), Dick Raub (Northwestern), Roy Lucke (Northwestern),

Dusty Powell (LCDOT), Bruce Christensen (LCDOT), Jack Gasinski

(Metra), Robert Alberton (RCL via phone)

Mike Flynn called the meeting to order at 10:00 a.m. Mr. Flynn explained that this is the first of the quarterly meetings required by the ICC order. Its purpose is to discuss the operation of the automated train horn system. In accordance with the order, only the Canadian National and the Village of Mundelein are required to meet quarterly to discuss operation of the system. However, members from all the departments participating in the task force were invited to this meeting in case they had comments regarding the operation of the system.

Automated Horn Malfunctions. Mr. Flynn explained that automated horn system malfunction is understood to mean a failure of the automated horn that causes the confirmation signals to shut off. Whenever this occurs, the train engineer is required to sound their horn. Mr. Flynn has been reporting such malfunctions in his monthly reports to the ICC. Discussions centered on making sure that all such incidents are recorded properly. Robert Alberton indicated that he will send Mr. Flynn a log of all service calls which can be included in future reports to the ICC.

Mike Barron reported that the Canadian National has had no negative feedback regarding the operation of the automated horn system. From their perspective the system appears to be running smoothly.

Mr. Flynn noted that on one prior occasion during a period when the confirmation signals were not working, a train crew was observed *not* sounding the horn at the Park Street crossing. Mike Barron instructed the group that whenever this is observed, the Canadian National should be notified and provided with the date, time and location, and if possible, the engine number.

Crossing Gate Malfunctions. Mr. Flynn reported that when crossing gates malfunction and remain in the down position, the automated horn is activated. In these instances, when Village personnel respond they have procedures to silence the horns until the gates are repaired, at which time the automated horn system is activated. Everyone agreed that this practice seems to be working smoothly. There were no negative comments regarding the intersections not within the Village of Mundelein. Village personnel would not typically respond to gate malfunctions at Winchester Road or Peterson Road. Libertyville police and Public Works have been trained in these procedures and they have reported no negative comments.

Malfunctions Reporting Protocol. The committee reviewed the Village of Mundelein's protocol for reporting malfunctions. The consensus was that everyone is clear and operating smoothly.

Input from Railroad Engineers. Mike Barron reported that he has received no negative comments from train engineers. Crews have adjusted to the confirmation signals.

Jack Palach reported that the signal maintainers have had no problems dealing with the automated horn system.

Blinder Installation. Mike Flynn reported that RCL has installed extended blinders at Route 60 and Hawley Street on the confirmation signals in order to deflect the light from the signals. The installation appears to have reduced the visibility to the motorist without affecting the visibility by the train crews. The blinders appear to be useful only at certain crossings that are perpendicular to the tracks.

Survey of Engineers. Dick Raub explained that a survey of railroad engineers would be included as part of the final report. The survey will be mailed shortly. The survey will also include input from the general public of Mundelein.

Public Perception. Public perceptions and input was discussed. The general perception is that the horns are a great addition and greatly reduce disturbance. Dick Raub explained that the final sound studies, survey of the engineers, survey of the public, and report on violations should be prepared in September with the draft final report issued in October 2002.

Next Meeting. The group decided that the next meeting would be in October 2002. The specific date will be chosen later. It was agreed that all parties would be invited to the meeting to provide comment.

The meeting adjourned at 11:00 a.m.

Minutes taken by: M/ws I

Assistant Village Administrator



# VILLAGE OF MUNDELEIN

Marilyn Sindles, Mayor

Pamela Keeney, Clerk

440 East Hawley Street Mundelein, IL 60060 www.mundelein.org Telephone: (847) 949-3200 Fax: (847) 949-0143 info@mundelein.org

August 28, 2002

Mr. Kurt Anderson Railroad Controls Limited 500 South Freeway Fort Worth, TX 76104

Dear Kurt:

Earlier this summer Railroad Controls installed "blinders" at the automated horn system signals at Route 60 and Hawley Street. The blinders are intended to reduce the glare from the blinking confirmation signals to the motorists. I have asked for staff input on these devices and discussed them at the first quarterly operations meeting held on August 22, 2002. Our feeling is that initially there were a number of calls regarding the signals, but over time comment has subsided. We feel that the blinders have provided some relief to the motorists, but are effective only at those crossings that are perpendicular to the tracks. Where crossings are angled, such as Butterfield Road, the shielding effect of the blinders would be ineffective.

We recommend that the blinders be added to Allanson, Park Street, Route 176, Dunbar, Peterson and Winchester. If the sides could be a little longer the shields might be even more effective.

Sincerely,

Michael A. Flynn

Assistant Village Administrator

MAF/ch

cc:

Bob Berry, ICC

Date	City	Crossing	Complaint
3-16-02	Mundelein	STH 60	improper blow sequence
3-18-02	Mundelein	Dunbar	error 3 on term slave
3-19-02	Mundelein	Dunbar	no conf./low voltage to VRD
3-20-02	Mundelein	Winchester	no power to slave
3-25-02	Mundelein	Park St.	no confirmation/ found error code 3 on vib
3-25-02	Mundelein	Peterson	no confirmation/error code 3 on slave
3-31-02	Mundelein	STH 60	error code 3 on vib
3-31-02	Mundelein	Alanson	error 13 on master control board
4-2-02	Mundelein	STH 60	error code 3 on vib
4-4-02	Mundelein	Butterfield	no confirmation of horn blowing
5-22-02	Mundelein	Alanson	heartbeat LED on main control board on solid
5-22-02	Mundelein	Park St.	no conf./slave error code 3
5-30-02	Mundelein	STH 60	no confirmation/error code 3 on slave
5-30-02	Mundelein	Winchester	no confirmation/error code 3 on slave
6-12-02	Mundelein	Park	VRD was damaged
6-16-02	Mundelein	all crossings	Intermittent Detector Failures
6-24-02	Mundelein	STH 60	no conf./slave error code 3
6-24-02	Mundelein	Maple Ave.	no confirmation/error code 3 on Master
7/29/02	Mundelein	STH 60	Slave Board Error Code 3
7/31/02	Mundelein	STH 60	Slave Board Error Code 3
8/21/02	Mundelein	Dunbar	no confirmation/ VIB error code 3
8/22/02	Mundelein	STH 60	power supply damaged

Person Reporting	Repair	
Phil H.(RCL)	replaced bad VRD	
Phil H.(RCL)	replaced horn board	
Phil H.(RCL)	repaired wiring problem	
Phil H.(RCL)	repaired wiring problem	
WCL/Chris W.(RCL)	Reset board error went away/sent replacement board 3-26	
WCL/Chris W.(RCL)	Reset board could not duplicate possibly weather related	
Chris W.(RCL)	reset	
Chris W.(RCL)	reset	
Chris W.(RCL)	reset	
WCL/Chris W.(RCL)	reset	
WCL/ Allan(RCL)	Reset Board Sent replacement, to be installed 5/24/02	
WCL/ Allan(RCL)	found loose Wagos on slave board/ repaired and reset	
WCL/Chris W.(RCL)	Reset and checked connections to speaker and det.	
WCL/Chris W.(RCL)	Reset and checked connections to speaker and det.	
Allan Chambers(RCL)	VRD replaced system up and running	
Allan Chambers, Chris W.(RCL)	All IC10 Chips replaced with new software	
WCL/Jeff Minnis	reset	
WCL/Jeff Minnis	reset	
CN Dispatch	Replaced Detection speaker Slave Side	
CN Dispatch	Replaced Slave Board and put V020731 software in	
CN Dispatch	Replaced VIB	
CN Dispatch	Replaced Power Supply	